

Custom Gun

... NO GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 BDLGENERAL CONDITION: GOODR #: 001432OUTSIDE WORK: SCOPE MOUNTEDDATE: 1-16-73FROM: BEIRICH AMMUNITION CORP.FIRED AMMO TYPE: -ROCHESTER, N.Y.

& CONDITION: _____

GUN #: 375936PROOF: R.E.P.INSP.: UTEST: 87CODE: ER = 10/68HEADING: O.K.GA./CAL.: 3006BREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

CONSIDERABLE DIRT INCLUDING METAL PARTICLES
INSIDE HOUSING. HARDENED LUBRICATION ON TRIGGER.
CONNECTOR = 1.083 (1.080 MODEL DRAWING) TRIGGER = 1.076
(1.076 MODEL DRAWING) SAFETY & TO CAM = .291 (1.292 MODEL
1.079 DRAWING)

COMPLAINT: "FIRES WITH SAFETY ON"INCIDENT: FOLLOW DOWN

COMMENTS: THE CONNECTOR CAN WORK UP TO INTERFERE
WITH THE SEAR AND PREVENT RETRACTION INTO
COCKED POSITION.

PLAINTIFF'S
EXHIBIT

3179