

Cust Coupl

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: GOOD R #: 000394
OUTSIDE WORK: NO DATE: 1-9-73
FROM: JOHN'S SPORTS CENTER
FIRED AMMO TYPE: - PITTSBURGH, KAN.
& CONDITION: _____ GUN #: 6432940
PROOF: R.E.P.-4 INSP.: 73 TEST: B4 CODE: CU-4/71
HEADING: - GA./CAL.: 243 WIN.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

BOLT CAM MARRED BY SAFETY. GROOVE CUT INTO
LEFT REAR OF HOUSING BY FIRING PIN HEAD. SEAR-
TRIGGER CONNECTOR ENGAGEMENT .015 (MIN. IS .020)
CONNECTOR BINDING ON TRIGGER.

COMPLAINT: "WENT OFF WHEN THE BOLT WAS CLOSED"

INCIDENT: FOLLOW DOWN

PLAINTIFF'S
EXHIBIT

3184

COMMENTS: THE TRIGGER CONNECTOR PROBABLY FAILED TO
RETRACT INTO POSITION UNDER THE SEAR, ALLOWING
THE FIRING PIN TO FOLLOW DOWN.