

Cust. Compl.

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 027329
OUTSIDE WORK: NO DATE: 1-2-73
FIRE AMMO TYPE: ✓ FROM: OSHMAN'S SPORTING GDS. CO.
& CONDITION: ASSEMBLER 56 BEAUMONT, TEXAS.
PROOF: R.E.P.-M INSP. 73 TEST: 13 GUN #: 6521466
HEADING: O.K. CODE: AW = 3/72
BREECH OPENING: - GR./CAL.: 3006
RECOIL SHOULDERS: O.K. CHECKED BY: CIPROSSER
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: GUN FIRED WHEN SAFETY WAS REMOVEDINCIDENT: FOLLOW DOWNCOMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BE
DUPLICATED. THE PRESENCE OF EXCESSIVE LUBRICANT
POSSIBLY CONTRIBUTED TO POOR TRIGGER RETRACT-
ION AND CAUSED FOLLOW DOWN.PLAINTIFF'S
EXHIBIT

3187

AL 0029717