

Model 710 safety

Discussion Thread

Response (Jason)

11/26/2003 8:59:04 AM

Dear Jeffrey:

Thanks for your inquiry. This is a normal condition with the 710. The 710 safety is a sear block safety. Once the sear has been released, it is in the way of the safety and the firing pin must be recocked to allow the safety to engage. Please let us know if you have further questions.

Customer (Jeffrey Scott)

11/22/2003 7:44:23 AM

I have noticed that once the 710 is fired (dry fired for example, and NOT recocked), the safety will not go into the on position. Is this normal? Thanks...