

stiff rotation on 710 270cal bolt

Discussion Thread

Response (Chris)

4/13/2005 2:52:58 PM

Dear Mr. McClanahan,

Thank you for your inquiry. We began production about mid-year on the 710 without the ISS safety. We apologize for any confusion. The 710 and the 597 will no longer have the ISS safety after 2004.

We apologize for any inconvenience you may be experiencing. We recommend taking/shipping the firearm to one of the following Remington Premier Repair Centers for inspection.

Paducah Shooters Supply, Inc.
3919 Cairo St.
Paducah, KY 42001
Phone: 270-442-3242
Fax: 270-442-5022

You can find additional Remington Warranty Centers for the US and internationally at the following section of our site.

<http://www.remington.com/repairsvc/modelselection.asp>

To view the warranty for Remington firearms, go to:

<http://www.remington.com/support/warranty.htm>

Customer (JIM MC CLANAHAN)

4/9/2005 5:46:31 PM

Also I was told by the dealer that this rifle didn't have the bolt lock security feature is this correct