

REPAIR CODE	MALFUNCTION
101	ACCURACY
185	3 SHOT PLUG AT WRONG END OF MAG TUBE
151	ACTION BAR IS BROKEN
194	ACTION BAR LOCK CATCHES BETWEEN ACTION BAR AND RECEIVER
195	ACTION CLOSURES TOO EASILY
140	ACTION IS DIFFICULT TO OPEN
186	ACTION SPRING TUBE FELL OFF
223	ACTION TUBE RING BROKEN
196	ACTUATING ROD BENT/LOOSE
102	BALANCE OF FIREARM IS NEEDED TO PERFORM PROPER REPAIR
173	BARREL BRACKET OUT OF POSITION
187	BARREL GUIDE STUD MISSING
245	BARREL IS BENT
188	BARREL SUPPORT SEPARATED FROM MAG TUBE
179	BARREL TO RECEIVER MISALIGNMENT
132	BLUING SALTS ARE BLEEDING FROM METAL
155	BOLT FACE/SHROUD DAMAGED
145	BOLT HANDLE FELL OFF BOLT IS BROKEN
240	BOLT LOCK SAFETY MOD
174	BOLT STOP STICKS
156	BORE IS HEAT CHECKED
224	BREECH PLUG FROZEN IN CHAMBER
181	BURR AT RIM AREA OF CHAMBER
103	BUTT PLATE/RECOIL PAD IS BROKEN
171	CAMO FINISH WORN/DAMAGED
219	CARDBOARD PACKING RING WAS NOT REMOVED
189	CARRIER LATCH IS BROKEN
193	CARRIER LATCH TAB IS OUT OF ADJUSTMENT
182	CARRIER OUT OF ADJUSTMENT
128	CHAMBER DIRTY/RUSTY
104	CHAMBER ROUGH/RINGS/TEARS/TIGHT
248	CHAMBER UPSET AT EXTRACTOR SLOT
157	CHOKE TUBE CONCENTRICITY
197	CHOKE TUBE CONCENTRICITY - BOTTOM BARREL
198	CHOKE TUBE CONCENTRICITY - TOP BARREL
158	CHOKE TUBE CRACKED
159	CHOKE TUBE THREADS ARE DAMAGED
238	CLEAN & INSPECT (200 TRIGGER ASSM ONLY)
172	CLOSES HARD OVER SHELL
199	COCKING RODS BIND
105	CONSIGNEE GUN
106	COULD NOT DUPLICATE CUSTOMER'S COMPLAINT
107	CREDIT RETURN
108	DAMAGE APPEARS TO HAVE OCCURRED IN TRANSIT
109	DAMAGES CASES, BULLETS OR SHELLS
200	DEBRIS UNDER REAR CONNECTOR
201	DOUBLES
201	EJECTOR - BOTTOM BARREL EJECTS TOO SOON
152	EJECTOR BROKEN