

Model 7400:

- Ken advised the team that he has recently had four complaints that the new Model 7400 fore-end did not fit properly.
- Chris advised that the fore-end was slightly altered but it should not be very noticeable. Chris asked for Ken to have examples sent.

Law Enforcement:

- Greg addressed the team about concerns with the Model 700 receiver face not square and fitting in the HS Precision stocks.
- Chris advised that the issue is with the HS Precision stocks.
- John T --- 100% of the receivers should be getting checked with a gauge.
- John T wanted to know if we could prove that it is an HS Precision problem. Chris advised that we just fix the stock. John T asked why we would fix the stock, how would HS Precision know that there is a problem. HS Precision is very slow to respond was the response.

Other:

- Danny asked the group if they had been hearing or seeing any problems with miss packed Model 870 combos (wrong bbl sent, two of the same bbl, etc.). Danny has received a few complaints from Canadian customers. Danny was asked to have samples sent in so that the issue could be addressed. Because of licensing issues we are looking for some domestic samples.

Notes:

- **Next meeting will be held on March 9th, 11:00 am – Noon. If you cannot attend or if you need to me to send you another meeting reminder so that you can save it, please let me know.**
- **Steve to follow up on the accurizing process and Danny to follow up with his finding on triggers adjusted outside of factory specs.**
- **Please let me know in advance of the meeting if there are any quality concerns that need to be added to the agenda.**

Confidential

Page 3

6/5/2006