

1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: NEW R #: 027515
 OUTSIDE WORK: NO DATE: 12-22-72
 FROM: MORLEY BRO.
 FIRED AMMO TYPE: _____ SAGINAW, MICH.
 & CONDITION: _____ GUN #: 6241128
 PROOF: R.E.P.-K INSP. 73 TEST: 13 CODE: KU=5/71
 HEADING: - OK./CAL.: 25-06
 BRESCHE OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: EXCESSIVE RADIUS-REAR APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: _____ APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT.025
BURRS ON TRIGGER. TRIGGER TOO CLOSE TO
GUARD ON RIGHT SIDE. THERE ARE INDICATIONS
OF PRIMER PIERCING ON FIRING PIN ASSEMBLY.

COMPLAINT: "WILL FIRE DURING FEEDING OPERATION."

INCIDENT: FOLLOW DOWN.

COMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BE
DUPLICATED. TRIGGER BIND MAY HAVE PREVENTED
PROPER RETRACTION.

PLAINTIFF'S
EXHIBIT

3189

AL 0029719