

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: GOOD R #: 026555
 OUTSIDE WORK: SCOPE MOUNTED DATE: 12-18-72
 FIRED AMMO TYPE: _____ FROM: Sgt. WIS. SPT. CENT.
 & CONDITION: _____ BELOIT, WIS.
 PROOF: R.E.P.-B INSP.: 73 TEST: 97 GUN #: 6580387
 HEADING: O.K. CODE: OW = 7/72
 BREACH OPENING: - AL./CAL.: 3006
 RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSER
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

HEAVY LUBRICANT AROUND SEAR BURR AT REAR OF
HOUSING FROM FIRING PIN HEAD.

COMPLAINT: "FIRES SOMETIMES WITH SAFETY ON"

INCIDENT: PROBABLY FOLLOW-DOWN.

COMMENTS: THE HEAVY LUBRICANT COMBINED WITH SEAR-
BIND PROBABLY HELD THE SEAR IN FIRED POSITION
AND CAUSED FOLLOW-DOWN.

PLAINTIFF'S
EXHIBIT

3191

AL 0029721