

700 Cust. Comp

1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: GOOD R #: 025940
 OUTSIDE WORK: BATT PAD ADDED, TRIGGER DATE: 12-15-72
PULL RE-ADJUSTED. FROM: BEST PRODUCTS
 FIRED AMMO TYPE: _____ HAMPTON, VA.
 & CONDITION: _____ GUN #: 6517902
 PROOF: R.E.P.-8 INSP. 58 TEST: 97 CODE: BW = 1/72
 HEADING: O.K. ON INSPECTION MAX. GA./CAL.: 3006
 BREECH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER BINDING ON GUARD, TRIGGER PULL ADJUSTED
DOWN TO 2-2 1/2 LBS. BY CUSTOMER. EXCESSIVE LUBRICANT.

COMPLAINT: GUN FIRES WHEN SAFETY IS RELEASED.

INCIDENT: FOLLOW DOWN.

COMMENTS: CUSTOMER'S MALFUNCTION NOT DUPLICATED,

HOWEVER WITH TRIGGER PULL REDUCED BELOW
SPECIFICATIONS (3 TO 5 LBS.) THE BINDING TRIGGER
PROBABLY DID NOT RETRACT SUFFICIENTLY TO LOCK THE
FIRING PIN.

PLAINTIFF'S
EXHIBIT

3195

AL 0029725