

710 *Cust. Complaint*

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: NEW R #: 025800
 OUTSIDE WORK: NO DATE: 12-14-72
 FROM: BILL'S SPORTS & HOBBY SHOP,
 ONEONTA, N.Y.
 FIRED AMMO TYPE: _____ GUN #: 6365666
 & CONDITION: _____ CODE: WT = 8/70
 PROOF: R.F.P.-C INSP. # 88 TEST: 29
 HEADING: O.K. GA./CAL.: 3006
 BREACH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .015 (MIN. IS .020)
 CONNECTOR CLEARANCE ON TRIGGER = 1.073 (MODEL DRAWING = 1.079)
 BURRS ON TOP SIDES OF TRIGGER.

COMPLAINT: GUN FIRED WHEN SAFETY WAS PUSHED OFF.

INCIDENT: FOLLOW DOWN.

COMMENTS: THE TRIGGER BIND COULD CAUSE FAILURE TO
 RETRACT AND FOLLOW DOWN, THE UNDER MIN. ENGAG-
 EMENT CONTRIBUTING TO THE MALFUNCTION.

PLAINTIFF'S
EXHIBIT

3136

AL 0029726