

Just Complaint

44-61

IN EXAMINATION REPORT NUMBER: _____

MODEL: 700

WORK: NEW

R # : 025981

QUANTITY: NO

DATE: 12-7-72

FIRED NO TYPE: _____

FROM: GRAF & SONS INC.

MEXICO, MO.

GUN # : 6439493

CODE: KU=5/71

& CONDITION: _____

PROOF: R.E.P.-L INSP.: 73 TEST: 53

HEADING: O.K.

GA./CAL.: 25-06

BREECH OPENING: _____

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

FEAR-TRIGGER CONNECTOR ENGAGEMENT, 0.10 (MIN. 15.020)

BURRS ON SIDE OF TRIGGER.

COMPLAINT: 'GUN GOES OFF WHEN BOLT IS CLOSED.'

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION NOT DUPLICATED,
HOWEVER THE TRIGGER BIND COMBINED WITH UNDER
MIN. ENGAGEMENT MAY HAVE CAUSED A FOLLOW
DOWN.

PLAINTIFF'S
EXHIBIT

3197

AL 0029727