

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: GOOD R #: 025024
OUTSIDE WORK: SCOPE MOUNTED, ALL DATE: 12-5-72
TRIGGER ADJUSTMENTS CHANGED. FROM: COMMUNITY HDQ. CO.
FIRED AMMO TYPE: - THOMASVILLE, N.C.
& CONDITION: ASSEMBLER IS GUN #: 6338169
PROOF: R.E.P. INSP.: 9 TEST: 87 CODE: KT-5/70
HEADING: O.K. GA./CAL.: 25-06
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: 15 ROUNDS - NO PIERCING APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN, SEAR DAMAGED. PRIMER
PIERCING IS INDICATED.

COMPLAINT: "BOLT FIRES WHEN YOU PUSH IT DOWN."

INCIDENT: FOLLOW DOWN.

COMMENTS: WITH THE TRIGGER CONNECTOR BROKEN THERE IS NO WAY
THE ACTION CAN BE COCKED. THE BREAK DOWN EVIDENTLY
STARTED WITH PRIMER PIERCING.

PLAINTIFF'S
EXHIBIT

3198

1/11
AL 0029728