

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: NEW R #: 026064
 OUTSIDE WORK: SCOPE MOUNTED DATE: 12-5-72
 FROM: HERTER'S INC.
 FIRED AMMO TYPE: _____ OLYMPIA, WASH.
 & CONDITION: _____ GUN #: 6524373
 PROOF: R.E.P.-B INSP. 74 TEST: 97 CODE: CW = 4/72
 HEADING: O.K. GR./CAL.: 300G
 BRESC OPENING: _____ CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .025(MIN) IS
.020) CONNECTOR = 1.088 MODEL DRAWING = 1.088, TRIGGER
MEASURES 1.074, MODEL DRAWING = 1.076
1.079

COMPLAINT: "FIRES WHEN SAFETY IS PUSHED OFF"

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BE
DUPLICATED, HOWEVER, THE .007 OVER MAX. CLEARANCE
BETWEEN THE TRIGGER AND CONNECTOR WILL ALLOW
THE CONNECTOR TO INTERFERE WITH THE SEAR AND
FAILING TO RETRACT INTO COCKED POSITION, CAUSE
A FOLLOW-DOWN.

PLAINTIFF'S
EXHIBIT

3199

AL 0029729