

NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700BOL  
 GENERAL CONDITION: NEW R #: 024573  
 OUTSIDE WORK: SCOPE & RECOIL PAD FITTED. DATE: 11-27-72  
 FROM: FRONTIERSMAN SPORTS INC.  
 MINNEAPOLIS, MINN.  
 FIRED AMMO TYPE: \_\_\_\_\_  
 GUN #: 6365254  
 & CONDITION: ASSEMBLER 72  
 PROOF: R.E.P. INSP. 74 TEST: 49 CODE: DT = 9/70  
 HEADING: O.K. OK./CAL.: 3006  
 BREACH OPENING: - CHECKED BY: C. PROSSER  
 RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_  
 CHAMBER: O.K. APPROVED: \_\_\_\_\_  
 TEST: NO APPROVED: \_\_\_\_\_  
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

SEAR-TRIGGER CONNECTOR ENGAGEMENT .005 (MIN. = .020)

TRIGGER CONNECTOR CLEARANCE ON TRIGGER = 1.075,

M/D = 1.076, 1.079; TRIGGER CLEARANCE ON CONNECTOR = 1.086,

M/D = 1.080, 1.083, FIRING PIN CAN CATCH ON REAR CORNER OF HOUSING. LAPPING ON CONNECTOR CROOKED.

COMPLAINT: RIFLE DISCHARGED WHEN LOADING CARTRIDGE.

INCIDENT: FOLLOW DOWN

COMMENTS: THERE IS EVIDENCE OF TRIGGER BIND. THIS COMBINED  
 WITH UNDER MIN. ENGAGEMENT AND EXCESSIVE TRIGGER  
 CONNECTOR CLEARANCE, CAUSES FOLLOW DOWN.

PLAINTIFF'S  
EXHIBIT

3200

AL 0029730