

Will James

From: James, Will
Sent: 08/10/2005 12:11:29 PM
To: Vicars, Gerald; Lance, Kevin D.; Williams, Gary; Boyles, Derek; Norton, Vince
CC:
BCC:
Subject: RE: M710 Short Action_8_9_05.doc

Thanks for the meeting notes. Just a few questions:

- 1) How much time on average between first article inspection date and Production run if we can assume parts are to print?
- 2) Ownership of changes to Owners Manual and Field Service Manual if necessary.
- 3) SPL Issues: You have called out the Sear Pivot Pin. Are you referring to the Sear Retaining Pin EXP9501?

Thanks again, Will

From: Vicars, Gerald
Sent: Wednesday, August 10, 2005 11:22 AM
To: Lance, Kevin D.; Williams, Gary; Boyles, Derek; James, Will; Norton, Vince
Subject: M710 Short Action_8_9_05.doc

M710 Short Action Meeting Issues

Subject to Protective Order - Williams v. Remington

BARBER 5.30.06R0000996

ETE00000095