

Remington
870 Remington Drive
Madison, North Carolina 27025-0700

Source:
North American Hunter, August 2002; page 103

Added 5/25/03

**REMINGTON
MODEL 600, 660, MOHAWK 600, RIFLES**

RECALL: The Remington Arms Company, Inc. announced today that under certain unusual circumstances on some of its centerfire bolt-action rifles, the safety selector and trigger could be manipulated in such a way that subsequently moving the selector to the fire position could result in accidental discharge. Remington firearms involved are **Model 600, 660, and Mohawk 600 rifles** manufactured prior to February 1975.

The difficulty can be corrected by installation of a new trigger assembly. In view of the potential safety hazard, the Company is recalling all of these guns produced prior to February 1975 for inspection and modification as required. Efforts are being made to contact owners of these guns. Individuals who have Model 600, 660 and Mohawk 600 rifles involved in the recall should write to:

**Remington Arms Company, Inc.
Bridgeport, CT 06602**

Or call:

800-241-8444 (all states),
GA residents call 800-282-1333.

Customers should give the operator the model and serial numbers of their gun when calling. Serial numbers involved in the recall are as follows:

Model 600 #0001 to 131,552
Model 660 #0001 to 131,552
Model Mohawk 600 #6,200,000 to 6,899,999

Source:

- **AFTE Journal, January 1979; Volume 11, Number 1:19**
 - **Shooting Times, January 1993; page 9**
-