

Remington.

SPL Issues – Timing TBD

Prepare to move on SPL no later than 11/30/05

- Receiver Insert
- Insert Support Bracket
- Sear Pivot Pin
- Stock Modification