

P.I. NO GUN EXAMINATION REPORT NUMBER: _____

GENERAL CONDITION: NEW

OUTSIDE WORK: NO

FIRE AMMO TYPE: _____

& CONDITION: _____

PROOF: R.E.P.-L INSP.: 72 TEST: 53

HEADING: O.K.

BRECH OPENING: -

RECOIL SHOULDERS: O.K.

CHAMBER: O.K.

TEST: NO

COMPONENT CONDITION: (Damaged, Broken, Old Style)

MODEL: 700 BDL

R #: 023622

DATE: 11-15-72

FROM: MONTGOMERY WARD

RICHMOND, CAL.

GUN #: 647155B

CODE: WU: 8/71

GA./CAL.: 3006

CHECKED BY: C. PROSSER

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .025

TRIGGER HOUSING PROTRUDING INTO FIRING PIN

HEAD CLEARANCE SO FIRING PIN HEAD CAN BE

PREVENTED FROM ASSUMING ITS POSITION AGAINST

THE SEAR.

COMPLAINT: FIRE WHEN SAFETY IS PUSHED OFF.

INCIDENT: FOLLOW DOWN

COMMENTS: THE INTERFERENCE BETWEEN FIRING PIN

HEAD AND HOUSING CREATES A BUMP WHICH

CAUSES SEAR BIND. SEAR STICKS DOWN IN

POSITION RESULTING IN FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3204

AL 0029734