

Cost Complaint

No GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 BDL

GENERAL CONDITION: NEW

R #: 023451

OUTSIDE WORK: NO

DATE: 11-13-72

FROM: RON SHIRKS
SHOOTERS SUPPLIES.

FIRED AMMO TYPE: _____

LEBANON, PA.

& CONDITION: _____

GUN #: 6494579

PROOF: R.E.P.-M INSP.: U TEST: 84

CODE: RU = 11/71

HEADING: O.K.

GA./CAL.: 270 W.H.

BREACH OPENING: _____

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: No

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

TRIGGER ASSEMBLY COMPONENTS STUCK TOGETHER
MAKING IT INOPERABLE.

COMPLAINT: WONT COCK

INCIDENT: FOLLOWS DOWN.

COMMENTS: TRIGGER ASSEMBLY WAS RENDERED INOPERABLE
BY SOME HARDENED SUBSTANCE.PLAINTIFF'S
EXHIBIT

3205

AL 0029735