

Crest Arms.

1 No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDLGENERAL CONDITION: GOOD R# : 022218OUTSIDE WORK: SCOPE MOUNTED. TRIGGER DATE: 11-10-72PULL WEIGHT CHANGED. FROM: JOHN PAYNEFIRED AMMO TYPE: _____ MT. VIEW, ARK.& CONDITION: _____ GUN # : 6504815PROOF: R.E.P.-M INSP.: U TEST: 13 CODE: XU = 12/71HEADING: -O.K. GUN/CAL.: 222BRESCH OPENING: - CHECKED BY: C. PROSSERRECOIL SHOULDERS: EXCESSIVE RADIUS REAR-LUGS. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: No APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .025 (ADJUST-
MENT UNDISTURBED) TRIGGER STOP & ADJUSTING SCREWS
SEALS BROKEN. TRIGGER CONNECTOR WARPED.

COMPLAINT: RIFLE FIRED WHEN SAFETY WAS PUSHED OFF.INCIDENT: FOLLOW DOWN.PLAINTIFF'S
EXHIBIT

3207

COMMENTS: WITH THE TRIGGER PULL REDUCED TO TWO POUNDS
TRIGGER CONNECTOR RETRACTION WOULD BE ERRATIC.
THE WARPED CONNECTOR ALSO WOULD CAUSE ERRATIC
ENGAGEMENT AND COULD RESULT IN FOLLOW DOWN.

REMINO CUSTOMER REMINGTON DOES NOT
RECOMMEND UNDER THREE POUND TRIGGER PULL.