

*Antony
Complaint*

I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL

GENERAL CONDITION: GOOD R #: 022245

OUTSIDE WORK: SCOPE MOUNTED DATE: 10-30-72

FIRED AMMO TYPE: _____ FROM: LOAR JEWELRY CO.

& CONDITION: _____ GRAFTON, W. VA.

PROOF: R.E.P.-D INSP. 74 TEST: 49 GUN #: 6246723

HEADING: O.K. CODE: PS = 6/69

BREECH OPENING: - GR./CAL.: 7MM REM. MAG.

RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSER

CHAMBER: O.K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

RECEIVER AND BOLT RUSTED. SEAR-TRIGGER
CONNECTOR ENGAGEMENT .085 (MIN. .15, .020) BURRS
ON SIDES OF TRIGGER, TRIGGER CLEARANCE ON
CONNECTOR 1.085 MODEL DRAWING = 1.080
CLEARANCE ON TRIGGER = 1.070 MODEL DWG. = 1.076
1.083 CONNECTOR
1.079

COMPLAINT: FIRES WHEN SAFETY IS MOVED TO OFF POSITION.

INCIDENT: FOLLOW DOWN

COMMENTS: THE EXCESSIVE CLEARANCE BETWEEN THE
TRIGGER AND CONNECTOR ALLOWS THE CONNECTOR
TO INTERFERE WITH THE SEAR, FAILING TO RETRACT
INTO COCKED POSITION.

PLAINTIFF'S
EXHIBIT

3208

AL 0029738