

Item #	Date Added	Priority	Model	Problem	Frequency of Complaint	Investigation Assignment	Investigation Completion Date	Investigation Status	Corrective Action	Corrective Action Responsibility
1	20-Apr	2	SP10	magazine cap swivel separating from cap.	replacing 2-3 caps per week.	Joe D., and Stew B.		proposed to add a new washer for new production next year.	checking on when the new washer is being added.	Stuart
2	22-Jun	1	300 Ideal	DOUBLE FIRES	FIVE TIMES AT OWAA mostly on O/U made after sn1250	Herd to keep a spread sheet on the repairs.		returning shotgun for inspection.		Stuart
3	22-Jun	3	300 Ideal	Stocks not fit well to guns. Wood to metal fit.	every gun in office.-5/29 shotguns in office as of now look good.			set new min-max. tool. For wood to metal fit		
4	7-Mar	2	870SM	Recoil pad going into the stk.	CSR receiving 3-4 calls a week.	Joe D.		checking date of mfg.	try putting a spacer in. no more than a 1/4" MAX. / Trying Gel pad.	waiting for John, and Al to now what we are doing. Need a fix asap.

Subject to Protective Order: Williams v. Remington