

	D	E
733	COULD NOT DUPLICATE CUSTOMERS COMPLAINT	X
734	CREDIT RETURN	X
735	DAMAGE APPEARS TO HAVE OCCURRED IN TRANSIT	X
736	DAMAGES CASES, BULLETS OR SHELLS	X
737	FAILS TO FIRE	X
738	FINISH IS DAMAGED ON TRIGGER GUARD/PLATE	X
739	HEADSPACE IS EXCESSIVE	X
740	MUZZLE DAMAGE	X
741	NO CORRESPONDENCE	X
742	NO FAULT FOUND AT BENCH	X
743	PACKING ERROR	X
744	POOR FINISH - BARREL	X
745	POOR FINISH - FORE END	X
746	POOR FINISH - RECEIVER (OR FRAME)	X
747	POOR FINISH - STOCK	X
748	RECEIVER IS MISCUT	X
749	RUSTED COMPONENT	X
750	SAFETY CONCERN, EXAMINED BY PRODUCT SERVICE	X
751	SIGHTS OFF CENTER	X
752	STOCK CRACKED	X
753	STOCK MARRED	X
754	TRIGGER PULL IS OUT OF FACTORY SPECS.	X
755	CHAMBER DIRTY / RUSTY	X
756	FAILS TO EXTRACT	X
757	HEADSPACE AT MINIMUM	X
758	LIGHT OR NO INDENT FROM FIRING PIN	X
759	BLUING SALTS ARE BLEEDING FROM METAL	X
760	EXTRACTOR MISSING	X
761	FAULTY MAGAZINE	X
762	TRIGGER CONNECTOR BINDS	X
763	EXTRACTOR IS BROKEN	X
764	FAILS TO EJECT	X
765	WILL NOT FEED PROPERLY	X
766	ACTION IS DIFFICULT TO OPEN	X
767	EXTRACTOR IS CATCHING ON SHELL HEAD	X
768	MAGAZINE DIFFICULT TO LOAD	X
769	POOR RECOIL PAD TO STOCK FIT	X
770	ROLL MARKING VISIBLE INSIDE BORE	X
771	BOLT HANDLE FELL OFF, BOLT IS BROKEN	X
772	FORE END CRACKED	X
773	FORE END FIT IS TOO TIGHT	X
774	FORE END IS TOO LOOSE	X
775	FORE END MARRED	X
776	GRIP CAP IS DAMAGED	X
777	ACTION BAR IS BROKEN	X
778	EJECTOR BROKEN	X
779	CHOKE TUBE CONCENTRICITY	X
780	CHOKE TUBE CRACKED	X
781	CHOKE TUBE THREADS ARE DAMAGED	X
782	FIRING PIN HITS PRIMER OFF CENTER	X
783	RECEIVER - EJECTOR IS LOOSE	X
784	RIB DOESN'T ALIGN WITH RECEIVER	X
785	RIB IS DAMAGED	X
786	RIB LANDS ARE LOOSE	X
787	RIB SWEEPS TO THE LEFT	X
788	RIB SWEEPS TO THE RIGHT	X
789	CAMO FINISH WORN/DAMAGED	X
790	BARREL TO RECEIVER MISALIGNMENT	X
791	BOLT - EXTRACTOR HITS INSIDE CHAMBER	X
792	BURR AT RIM AREA OF CHAMBER	X
793	CARRIER OUT OF ADJUSTMENT	X