	D	E ***
1038	GAS ORIFICE HOLE IS OVERSIZE	Х
1039	MAGAZINE TUBE SEPARATED FROM RECEIVER	, х
1040	3 SHOT PLUG AT WRONG END OF MAG TUBE	X
1041	ACTION SPRING TUBE FELL OFF	×
1042	BARREL GUIDE STUD MISSING	X
1043	BARREL SUPPORT SEPARATED FROM MAG TUBE	×
1044	CARRIER LATCH IS BROKEN	X
1045	GAS CYLINDER SEPARATED FROM BARREL	х 🤏
1046	GAS HOLES OUT OF POSITION	******
1047	TRIGGER - CARRIER LATCH TAB IS OUT OF ADJUSTMENT	×
1048	GAS CYL CRACKED	X
1049	INTERCEPTOR LATCH STUD MISSING	X
1050	CARDBOARD PACKING RING WAS NOT REMOVED	X
1051	PISTON/PISTON SEAL INCORRECTLY INSTALLED	X
1052	RECEIVER FEED CUTS ARE ROUGH	×
1053	•	
1054		
1055	- ````````````````````````````````````	*****320*****
	ACCURACY	жана Т ТТ Тан яно. Х
	BALANCE OF FIREARM IS NEEDED TO PERFORM PROPER REPAIR	× ^
	BUTT PLATE / RECOIL PAD IS BROKEN	x
	CHAMBER ROUGH / RINGS / TEARS / TIGHT	x
	CONSIGNED GUN	x
	COULD NOT DUPLICATE CUSTOMERS COMPLAINT	x
	CREDIT RETURN	x
Lucianiani	DAMAGE APPEARS TO HAVE OCCURRED IN TRANSIT	X
*********	DAMAGES CASES, BULLETS OR SHELLS	X
	FAILS TO FIRE	X
	FINISH IS DAMAGED ON TRIGGER GUARD/PLATE	X
	HEADSPACE IS EXCESSIVE	X
	MUZZLE DAMAGE	X
	NO CORRESPONDENCE	X
*************	NO FAULT FOUND AT BENCH	X
	PACKING ERROR	×
	POOR FINISH - BARREL	×
	POOR FINISH - FORE END	Х
	POOR FINISH - RECEIVER (OR FRAME)	X
	POOR FINISH - STOCK	X
	RECEIVER IS MISCUT	X
	RUSTED COMPONENT	X
1078	SAFETY CONCERN, EXAMINED BY PRODUCT SERVICE	Х
1079	SIGHTS OFF CENTER	X
1080	STOCK CRACKED	X
1081	STOCK MARRED	X
1082	STOCK MARRED TRIGGER PULL IS OUT OF FACTORY SPECS.	X
1083	CHAMBER DIRTY / RUSTY	Х
1084	FAILS TO EXTRACT	X
1085	HEADSPACE AT MINIMUM	×
	LIGHT OR NO INDENT FROM FIRING PIN	X
	BLUING SALTS ARE BLEEDING FROM METAL	X
	ACTION IS DIFFICULT TO OPEN	X
	POOR RECOIL PAD TO STOCK FIT	X
	ROLL MARKING VISIBLE INSIDE BORE	X
	FORE END CRACKED	X
	FORE END FIT IS TOO TIGHT	X
	FORE END IS TOO LOOSE	X
	FORE END MARRED	X
	GRIP CAP IS DAMAGED	X
	EJECTOR BROKEN	X
	CHOKE TUBE CONCENTRICITY	X
Linag	CHOKE TUBE CRACKED	X