

FAULT CATEGORY	OLD CODE	NEW CODE	MALFUNCTIONS
OUT OF SPECS	M001	M101	ACCURACY
MISCELLANEOUS	M052	M185	3 SHOT PLUG AT WRONG END OF MAG TUBE
BROKEN PART		M151	ACTION BAR IS BROKEN
FUNCTION		M194	ACTION BAR LOCK CATCHES BETWEEN ACTION BAR AND RECEIVER
MISCELLANEOUS		M195	ACTION CLOSSES TOO EASILY
MISCELLANEOUS		M140	ACTION IS DIFFICULT TO OPEN
BROKEN PART	M002	M188	ACTION SPRING TUBE FELL OFF
BROKEN PART		M223	ACTION TUBE RING BROKEN
FUNCTION		M196	ACTUATING ROD BENT/LOOSE
MISCELLANEOUS		M102	BALANCE OF FIREARM IS NEEDED TO PERFORM PROPER REPAIR
OUT OF SPECS	M043	M173	BARREL BRACKET OUT OF POSITION
BROKEN PART	M003	M187	BARREL GUIDE STUD MISSING
		M245	BARREL IS BENT
BROKEN PART	M004	M188	BARREL SUPPORT SEPARATED FROM MAG TUBE
OUT OF SPECS	M063	M179	BARREL TO RECEIVER MISALIGNMENT
OUT OF SPECS		M132	BLUING SALTS ARE BLEEDING FROM METAL
OUT OF SPECS	M041	M155	BOLT FACE / SHROUD DAMAGED
BROKEN PART	M005	M145	BOLT HANDLE FELL OFF, BOLT IS BROKEN
		M240	BOLT LOCK SAFETY MOD
OUT OF SPECS		M174	BOLT STOP STICKS
OUT OF SPECS	M035	M156	BORE IS HEAT CHECKED
OUT OF SPECS	M059	M224	BREECH PLUG FROZE IN BREECH
FUNCTION	M024	M181	BURR AT RIM AREA OF CHAMBER
BROKEN PART		M103	BUTT PLATE / RECOIL PAD IS BROKEN
FINISH	M048	M171	CAMO FINISH WORN/DAMAGED
MISCELLANEOUS		M219	CARDBOARD PACKING RING WAS NOT REMOVED
BROKEN PART		M189	CARRIER LATCH IS BROKEN
OUT OF SPECS		M193	CARRIER LATCH TAB IS OUT OF ADJUSTMENT
FUNCTION	M006	M182	CARRIER OUT OF ADJUSTMENT
OUT OF SPECS	M058	M128	CHAMBER DIRTY / RUSTY
OUT OF SPECS	M027	M104	CHAMBER ROUGH / RINGS / TEARS / TIGHT
		M248	CHAMBER UPSET AT EXCT SLOT
OUT OF SPECS	M007	M157	CHOKE TUBE CONCENTRICITY
OUT OF SPECS		M197	CHOKE TUBE CONCENTRICITY - BOTTOM BARREL
OUT OF SPECS		M198	CHOKE TUBE CONCENTRICITY - TOP BARREL
BROKEN PART		M158	CHOKE TUBE CRACKED
OUT OF SPECS		M159	CHOKE TUBE THREADS ARE DAMAGED
		M238	CLEAN & INSPECT (700 TRIGGER ASSM ONLY)
FUNCTION	M008	M172	CLOSES HARD OVER SHELL
FUNCTION		M199	COCKING RODS BIND
MISCELLANEOUS	M053	M105	CONSIGNED GUN
MISCELLANEOUS		M106	COULD NOT DUPLICATE CUSTOMERS COMPLAINT
MISCELLANEOUS	M062	M107	CREDIT RETURN
MISCELLANEOUS		M108	DAMAGE APPEARS TO HAVE OCCURRED IN TRANSIT
OUT OF SPECS	M064	M109	DAMAGES CASES, BULLETS OR SHELLS
MISCELLANEOUS		M200	DEBRIS UNDER REAR CONNECTOR
FUNCTION	M066	M201	DOUBLES
FUNCTION		M202	EJECTOR - BOTTOM BARREL EJECTS TOO SOON
BROKEN PART	M029	M152	EJECTOR BROKEN
FUNCTION		M180	EJECTOR DOES NOT HAVE ENOUGH TENSION
OUT OF SPECS		M164	EJECTOR IS LOOSE
OUT OF SPECS		M203	EJECTOR SEAR OUT OF ADJUSTMENT
OUT OF SPECS		M204	EJECTOR SEAR TOO LONG
BROKEN PART	M030	M225	EJECTOR SPRING IS BROKEN
OUT OF SPECS	M060	M161	EJECTOR STUCK IN BOLT
FUNCTION		M205	EJECTOR SYSTEM HAS INCORRECT TIMING
FUNCTION		M206	EJECTORS BIND
OUT OF SPECS		M180	EXTRACTOR HITS INSIDE CHAMBER