

FAULT CATEGORY	OLD CODE	NEW CODE	MALFUNCTIONS
BROKEN PART	M036	M236	RECEIVER BROKEN AT BARREL CLAMP
OUT OF SPECS		M221	RECEIVER FEED CUTS ARE ROUGH
OUT OF SPECS		M232	RECEIVER INSERT IS MISSING
OUT OF SPECS	M032	M121	RECEIVER IS MISCUT
BROKEN PART		M153	RECEIVER PLUG SCREWS BROKEN
OUT OF SPECS	M031	M154	RECEIVER SCOPE MOUNT HOLES OFF CENTER
		M239	REPLACED TRIGGER ASSEMBLY (700 ONLY)
OUT OF SPECS	M055	M233	RESIZE BORE
OUT OF SPECS	M055	M235	RESIZE BORE
		M241	RETURN GUN TO FACTORY
OUT OF SPECS	M049	M176	RETURNED FOR RECALL/UPDATE
OUT OF SPECS		M165	RIB DOESN'T ALIGN WITH RECEIVER
OUT OF SPECS		M166	RIB IS DAMAGED
BROKEN PART		M167	RIB LANDS ARE LOOSE
OUT OF SPECS		M167	RIB SWEEPS TO THE LEFT
OUT OF SPECS		M169	RIB SWEEPS TO THE RIGHT
OUT OF SPECS	M040	M139	RIFLING ROUGH / MISCUT / DAMAGED
OUT OF SPECS		M144	ROLL MARKING VISIBLE INSIDE BORE
FINISH	M019	M122	RUSTED COMPONENT
MISCELLANEOUS	M037	M123	SAFETY CONCERN. EXAMINED BY PRODUCT SERVICE
		M246	SAFETY SPRING INSPECTION/REPLACEMENT (710)
OUT OF SPECS	M039	M170	SCOPE MOUNT THREADS UPSET IN RECEIVER
		M243	SEE CUSTOMERS LETTER FOR MORE INFO
OUT OF SPECS	M020	M124	SIGHTS OFF CENTER
BROKEN PART	M021	M125	STOCK CRACKED
FINISH	M022	M126	STOCK MARRED
OUT OF SPECS	M065	M177	STOCK NOT BEDDED PROPERLY
OUT OF SPECS	M056	M178	TRIG ADJ SCREWS RESET. CANNOT READJUST
OUT OF SPECS		M135	TRIGGER CONNECTOR BINDS
OUT OF SPECS	M028	M127	TRIGGER PULL IS OUT OF FACTORY SPECS.
		M242	UPDATE (710 BACKERS & BOLT STOP)
		M244	UPDATE BOLT STOP
FUNCTION	M023	M138	WILL NOT FEED PROPERLY