

## Model 7

1983- Present

The Model 7 is only available in **short actions**. **The Model 7 replaced the Model 600 and the Model 660 of the 70's.**

### **Stocks:**

Synthetic stocks are available for the Model 7.

The Model 7 Youth can be converted to a full-sized Model 7 by changing the stock.

The extractor is probably broken, sticking, or misaligned if the **bolt closes very hard over the shell head and scars the rim**. Firearm should be serviced by an authorized repair station.

There could be a flaw near the end of the muzzle if the **rifle fails to group**. This is normally inspected by using a bore scope or with a magnifying glass. The barrel cannot be fixed; it must be replaced.

### **Trigger Pull and Safety**

The Model 7 trigger pull can be adjusted to a minimum 3 ½ pounds by an authorized gunsmith. Adjustments should not be made to the sear engagement screw.

Any problems with the firing mechanism should be handled by an authorized gunsmith (ex: safety that seems to work too hard).