

Model 7400

1982-Present

The 742 was replaced by the 7400. However, the 7400 was a complete redesign. The barrel, bolt, receiver, and action bar were improved to provide longer and more dependable service.

Accelerator ammunition can only be used if loaded single shot. If fed from the magazine, it will bind.

The bolt may drag when it comes in contact with the magazine box, especially when loaded with shells. This will **bind the action, restricting the action from working smoothly**. The magazine box can be adjusted down by changing the magazine latch. Latch numbers range from 0-4. A lower numbered latch may need to be installed. (EX: replace a number 3 latch with a number 2)

A dirty, rusty, and/or pitted chamber may cause the rim of casing to be marred.

When the shell is fired, the casing will expand into the dirt, rust, or pits, causing the casing to be damaged. Polishing the chamber may correct the problem. If not, the barrel must be replaced.