

## Model 7600

### 1982-Present

The Model 7600 replaced the Model 760. The barrel, bolt, receiver, and action bar were redesigned to provide longer and more dependable service.

Accelerator ammunition can only be used if loaded as a single shot. If fed from the magazine, it will bind.

The bolt may drag when it comes in contact with the magazine box, especially when loaded with shells. This will **bind the action, restricting the action from working smoothly.** The magazine box can be adjusted down by changing the magazine latch. Latch numbers range from 0-4. A lower numbered latch may need to be installed. (EX: replace a number 3 latch with a number 2)

A sharp edge leading into the chamber area of the barrel may cause the 7600 to **nick the tip of the bullet and jam when feeding a shell from the magazine into the chamber.** Changing the magazine latch or chamfering the leading edge may correct the problem.