

Malfunction Code	M-176 Returned For Recall/Up date	M-238 Clean & Inspect	M-239 Replace Trigger Assembly	M-240 Bolt Lock Safety Modificati on
40-X	0	0	0	1
600	43	0	4	4
600 Mohawk	30	0	8	8
660	14	0	4	3
700	6	0	188	79
721	1	0	41	14
722	0	0	23	5
XP 100	5	0	0	3
Total	99	0	268	117
	20%	0%	55%	24%

Backlog

Model	Approval Hold	Parts Hold
700/721	8	0
600/660	3	0
XP-100	0	0

By Malfunction Code - Repairs performed by RARC's

Frequency 1/3/03 to 12/31/03

Malfunction Code	M-176 Returned For Recall/Up date	M-238 Clean & Inspect	M-239 Replace Trigger Assembly	M-240 Bolt Lock Safety Modificati on
40-X	0	0	0	2
600	215	0	281	124
600 Mohawk	1	0	4	1
660	64	0	60	38
700	232	0	222	2295
721	25	0	37	238
722	14	0	15	78
XP 100	6	0	1	7
Total	557	0	620	2783
	14%	0%	16%	70%

Total RARC's warranty frequency 1/3/03 to 12/31/03 Submitted Claim Forms