

Crab-Camp.

No GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700GENERAL CONDITION: NEWR #: 020090OUTSIDE WORK: SCOPE MOUNTEDDATE: 10-10-72FROM: SOUTHERN GUN ^{INC.} DKFIRED AMMO TYPE: W-W SUPERMIAMI, FLORIDA

& CONDITION: _____

GUN #: 6562968PROOF: R.E.P.-M INSP.: 73 TEST: 59CODE: KW = 5/72

HEADING: _____

GA./CAL.: 7MM REM. MAG.BREACH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT, 020, STEEL
SHAVINGS BETWEEN SEAR AND HOUSING AT SEAR PIN
HOLE.

COMPLAINT: FIRES WHEN CLOSING BOLTINCIDENT: FOLLOW DOWN.

COMMENTS: THE STEEL SHAVINGS PROBABLY CAUSED THE
SEAR TO BIND AND FAILED TO RETRACT TO COCKED
POSITION THUS, FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3211

AL 0029741 ^{10/1}