

RD-6542-1 Rev. 2-15-61

P.I. No GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_

MODEL: 700

GENERAL CONDITION: NEW

R # : 019718

OUTSIDE WORK: No

DATE: 10-5-72

FROM: K MART ENTERPRISE

FIRE AMMO TYPE: -

ROYAL OAK, MICH.

& CONDITION: -

GUN # : 6258285

PROOF: R.E.P.-A INSP. 58 TEST: 49

CODE: 05 = 7/69

HEADING: O.K.

GR./CAL.: 3006

BREECH OPENING: -

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: \_\_\_\_\_

CHAMBER: O.K.

APPROVED: \_\_\_\_\_

TEST: No

APPROVED: \_\_\_\_\_

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: \_\_\_\_\_

SEAR - CONNECTOR ENGAGEMENT 010 (MIN. 15.020)

SOLIDIFIED LUBRICANT ON SIDE OF SEAR.

COMPLAINT: "FIRES WHEN EJECTING SHELLS"

INCIDENT: FOLLOW DOWN

COMMENTS: THE SOLIDIFIED LUBRICANT CAUSED THE SEAR  
TO STAY DOWN IN FIRED POSITION. WHEN THE REC-  
WAS ROTATED TO LOCK-UP, FOLLOW DOWN OCCURRED.

PLAINTIFF'S  
EXHIBIT

3212

AL 0029742