

Current Status

- Initial 100 rd proof test complete
 - Head space did not move during test.
 - The Firing Pin was piercing 90% of primers.
 - Firing Pin design was changed to incorporate a smaller, round firing pin tip.
 - A second 100 rd proof test will be conducted with the new firing pin.
- Drawing package complete on June 9th.
 - sent to Mayfield for review.