

GUN EXAMINATION REPORT NUMBER: GENERAL CONDITION: NEWOUTSIDE WORK: NOFIRED AMMO TYPE: FACTORY LOADS& CONDITION: PROOF: R.E.P.E INSP.: 74 TEST: 49HEADING: MAX. WITH ASSEMBLY MAX.BREACH OPENING: -RECOIL SHOULDERS: EXCESSIVE RADIUS BACK OFCHAMBER: O.K.TEST: NO

COMPONENT CONDITION: (Damaged, Broken, Old Style)

MODEL: 700 BDLR # : 015571DATE: 8-14-72FROM: HIGHSPIRE SPTG.
GROUPS INC.HIGHSPIRE, PA.GUN # : 6312165CODE: LT-2/70GA./CAL.: 3006CHECKED BY: C. PROSSERAPPROVED: APPROVED: APPROVED: APPROVED:

SEAR-TRIGGER CONNECTOR ENGAGEMENT .010 (MIN. IS .020)
BURRS ON SIDES OF UPPER PART OF TRIGGER SHOW FRICTION
MARKS. POOR COLOR ON BARREL AT REAR SIGHT.

COMPLAINT: "FIRES JUST AS BOLT IS CLOSED."INCIDENT: FOLLOW DOWN

COMMENTS: THE TRIGGER BIND WITH UNDER MIN. ENGAGEMENT
CAUSED ERRATIC TRIGGER RETRACTION AND FOLLOW
DOWN.

PLAINTIFF'S
EXHIBIT

3217

AL 0029747