

710 Initial Release

PRODUCT CONCERNS

- Action Difficult to Cycle
- Bolt Binds When Over Rotating

CORRECTIVE ACTION TAKEN

- Bolt Body Finish Changed from Bead Blast to High Polish Blued
- Designed Ribs to Fit in Backside of Receiver Insert to Provide Additional Support