

No GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 *Curt*GENERAL CONDITION: NEWR #: 013117OUTSIDE WORK: SCOPE MOUNTEDDATE: 6-19-72FIRED AMMO TYPE: -FROM: SPORTSMEN'S DENMT. SHASTA, CAL.& CONDITION: ASSEMBLER 65GUN #: 6249832PROOF: R.F.P.-D INSP.: 7ATEST: B7CODE: P5=6/69, CH3=4/72HEADING: O.K.GA./CAL.: 7MMBREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: No

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .010 (MIN=.020)BOTH SEAR AND CONNECTOR DAMAGED ON ENGAGEMENT CORNERS. CONDITION OF FIRING PIN HOLE & FIRING PIN POINT INDICATE PRIMER PIERCING HAS BEEN EXPERIENCED.COMPLAINT: WILL NOT FIREINCIDENT: FOLLOW DOWNCOMMENTS: THE CUSTOMER PROBABLY EXPERIENCED A PERCEDPRIMER WHICH WITH THE .010 ENGAGEMENT, CAUSED THE SEAR-CONNECTOR DAMAGE RESULTING IN FOLLOW-
DOWN.PLAINTIFF'S
EXHIBIT

3226

AL 0029758