

*M/115 Cigarette
Complaint*

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700

GENERAL CONDITION: NEW R #: 012925

OUTSIDE WORK: NO DATE: 6-14-72

FROM: LEO'S CUSTOM STAMPS

FIRE AMMO TYPE: _____ BETHEL PARK, PENN.

& CONDITION: _____ GUN #: 6445877

PROOF: R.E.P.N INSP.: 73 TEST: 13 CODE: PU-6/71

HEADING: O.K. GRA./CAL.: 17REM.

BRECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: NO - 20 ROUNDS WITH NO BLOWN PRIMERS APPROVED: _____

AFTER NEW BOLT, APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR'S SEAR ENGAGEMENT .010, BOTH
CORNERS BROKEN OFF, FIRING PIN ASSEMBLY RUSTED,
BOLT BODY STAINED & FIRING PIN HOLE AT HEADING SHARP.

COMPLAINT: WHEN HE CLOSED THE BOLT ON THE FOURTH ROUND
IT WENT OFF.

INCIDENT: FOLLOW DOWN.

COMMENTS: THE CORNER BREAKAGE ON THE SEAR AND
TRIGGER CONNECTOR, WHICH RESULTED IN FOLLOW-DOWN,
IS THE RESULT OF INSUFFICIENT ENGAGEMENT AND PRIMER
PIERCING.

PLAINTIFF'S
EXHIBIT

3227

AL 0029759