

My Remington 700 Classic .35 Whelen bolt kept coming open during my recent hu...

Discussion Thread

Response (Dell) 10/10/2000 6:35:56 PM  
At 10/10/2000 03:34 PM we wrote -  
Dear Mr. Elliott,

Thank you for your inquiry. We no longer offer the type of safety you are looking for. This type was discontinued in 1985. You may wish to contact an obsolete parts dealer.

For your convenience we have included a link below to a list of establishments that may be able to service your older Remington firearm:.

<a href="http://www.remington.com/support/parts/obsolete.htm" target="\_blank"><b>http://www.remington.com/support/parts/obsolete.htm</b></a>

Additional information regarding parts and service can be found in our Support Section under "Obtaining Services".

NOTE: This link will open a new browser window so that you can mark your question as solved (See the bottom of this Solution page). Please take the time to answer this question as it will help us better answer your questions in the future.

Customer (Rich Elliott) 10/6/2000 1:21:50 PM  
My Remington 700 Classic .35 Whelen bolt kept coming open during my recent hunt in that fir & spruce jungle that is Montana's Bob Marshall wilderness. It still has the receiver slot and bolt slot to accomdate the old style safety that locks the bolt shut. Can I get the old style safety with the bolt lock wing on it? I've had the same problem with my Remngton Classic .458 (Lott) in the Ethiopian rain forest but since we quit hunting elephants there that is a moot point.  
Regards  
Rich Elliott, Ethiopian Rift Valley Safaris