```
[Fwd: 700 BDL Accidental Discharge]
Discussion Thread
Response (Laura)
At 12/12/2000 09:46 AM we wrote -
                                         11/19/2001 11:30:26 AM
Dear Sir,
We cannot determine what steps will be necessary until we receive your
firearm and have it evaluated by our factory gunsmiths.
At 11/19/2001 11:29 AM we wrote -
Dear Mr. Nuich,
we have received your firearm at our factory. We could not duplicate the noted discharge, however our gunsmiths are replacing the trigger assembly
at no charge.
                                                12/9/2000 2:45:30 PM
Customer (Steve Nuich)
          ======== Message Attachment
"steve.nuich" wrote:
Subject:
Message-Id: <39CA5E17.000001.26112@rightnow01.up2.com>
Date: Thu, 21 Sep 2000 15:34331 -0400 (EDF)
To: steve.nuich@tlcd.com
From: info@remington.com
Subject: I have a mid 1970%s Model 700 BDL... [Incident:remington
000919-0078]
Content-Transfer-Engaging: guoted-printable
Recently you requested personal assistance from our on-line
support center. Below is a summary of your request and our=20
response.
If we do not hear from you within 48 hours we will assume your=20
issue has been resolved.
Thank you for allowing us to be of service to you.
```