

YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

Incident Details:

Reference #: 000919-0078

Topic: Firearms

Sub-Topic: Centerfire Rifles

Contact: steve.nuich@tcd.com

Date Created: 09/19/2000 08:09 PM

Last updated: 09/21/2000 03:14 PM

Elapsed Time: 1 Day, 19 Hours

Status: Unresolved

Model Number: Model 700 BDL

Description:

I have a mid 1970's Model 700 BDL in .30-06... was hunting this weekend and had an accidental discharge when I released the safety... the gun has less than 200 rounds fired through it... my brother stated that the same thing had happened to him once before... I posted a question about this on shooters.com message board and received replies from others that had the same experience and some said that Remington is aware of this and has a fix... if you do have a fix I would greatly appreciate it so I can avoid a