

the trigger was worked on by a gunsmith at an authorized Remington dealer and was very crisp and clean at a 3lb trigger pull.
> The work done was an improvement to the factory trigger and I hope your gunsmith shop can duplicate the trigger job done and not just replace the trigger group with a factory trigger group. As I
> stated before, the work done by the gunsmith was not the cause of the accidental discharge as both my father and brother experienced an AD with the rifle before I had the trigger worked on. Thank
> you.
> steve.nuich.vcf, 195 bytes, discarded