

1. Gun is a Model 700 BDL .308 Serial # 6306619
2. Gun discharged without trigger activation about 12 years ago, it was either on bolt closure or safety on/off. The round went into the ground, no injuries resulted. I hunted with the rifle many years before and many years after the incident without problems.
3. Gun was and is in near perfect condition, no rust on trigger mechanism.
4. After the accidental discharge, I brought gun to a gunsmith, who adjusted trigger mechanism, but now I don't really know if this fixed anything.
5. Please advise - The program said you are not responding to allegations on this matter, but you have a problem.

Michael E Larson  
N6267 Eleanore Lane  
Fond du Lac, WI 54935 Phone-920-922-8766 email melco@dotnet.com  
<mailto:melco@dotnet.com>

At 02/09/2001 09:15 PM you wrote -  
> Issue is resolved, am sending gun to Remington.  
Thank you for your quick response  
>  
>

At 02/15/2001 05:00 PM you wrote -  
> Firearm shipped Postal Service 02/12/01 for repair and return.  
I would like a document stating firearm was repaired, and  
should be safe from above stated problem, upon return.  
Thank you  
Mike  
>  
>