

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDLGENERAL CONDITION: GOOD R #: 12354OUTSIDE WORK: SCOPE MOUNTED, TRIGGER DATE: 6-16-71ASSEMBLY ADJUSTED (FRONT SCREWS) FROM: RON MCKINNEYFIRED AMMO TYPE: - THOMASTON, TEXAS& CONDITION: _____ GUN #: 6324285PROOF: R.E.P.-G ASSEMBLER AI INSP: 73 TEST: 87 CODE: AT-3/70HEADING: CLOSES ON MAY. HEADING DUMMY GA./CAL.: 25-06BREECH OPENING: - CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

FIRING PIN POINT FLAT ON SIDES, TRIGGER CONNECTOR
BROKEN, GRIP CAP OFF, RADINS AT REAR OF RECOIL
SHOULDERS ON BOLT.

COMPLAINT: "CANNOT GET THE TRIGGER TO STAY IN ADJUSTMENT,"
"WHEN I SHOOT THE RIFLE, THE FIRING PIN KNOCKS HOLES IN THE PRIMER,"

INCIDENT: FOLLOW-DOWN & PIERCED PRIMER.

COMMENTS: THE BROKEN TRIGGER CONNECTOR FAILING TO RETRACT
CAUSED THE FOLLOW-DOWN. PRIMER PIERCING MAY
HAVE BEEN CAUSED BY THE DEFORMED FIRING PIN POINT.

REPLACED TRIGGER CONNECTOR.REPLACED BOLT ASSEMBLY & FIRING PIN - SEE ABOVE.PLAINTIFF'S
EXHIBIT

3229

AL 0029761