

operates properly.

As the owner of many firearms of various brands, this is the first time I have ever had this experience with an out of the box firearm. Have you received any reports of similar problems with The Model 700? While I am confident with the adjustment that I made to the safety mechanism, do you have concerns with the rifle and if so, what suggestions might you have? As an employer of 200 people, most of them engaged in hunting and shooting

sports; a life member of the NRA, and the North American Hunting Club, I anxiously await your response.

You may contact me by e-mail at either mmcintyre737@cs.com or mmcintyre@quakercoal.com.

My home address is:

Mark McIntyre
67300 Country Club Road
Saint Clairsville, Ohio 43950
Home phone: 740-695-3841
work phone: 740-942-8220

Please contact me at your earliest convenience. Thank you!