

I have a Model 700 25-06. I cannot open the bolt to remove cartridges unless ...

Discussion Thread

Response (Laura) 2/20/2002 9:15:55 AM  
Dear Mr. Phillips,  
Thank you for this additional information. According to the serial number provided, this firearm was manufactured in or around 1972. This would be the reason for the different style of bolt lock safety. If you would like to have your older rifle changed to the non bolt lock safety, like on your newer firearm. We can do this at our factory for approximately \$25-\$50. You can find instructions for sending your firearm to us in the Support/Repair section of our website. You can also read more about these two designs in the safety section of our website.

Customer (Roger Phillips) 2/18/2002 8:21:30 PM  
If I am reading the serial number properly, it is located on the left side of the rifle immediately in front of the Remington Model 700 lettering on the chamber. The number reads 6518701. Does this help?

Thank you