

Customer Complaint

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL

GENERAL CONDITION: NEW R #: 010030

OUTSIDE WORK: NO DATE: 5-1-72

FIRED AMMO TYPE: _____ FROM: ODELL HOWE, CO.

& CONDITION: _____ GREENSBORO, N.C.

PROOF: R.F.E.-H INSP.: 51 TEST: 13 GUN #: 6429469

HEADING: O.K. CODE: EU-10/71

BREECH OPENING: - GA./CAL.: 3006

RECOIL SHOULDERS: O.K. CHECKED BY: C. PEDDER

CHAMBER: O.K. APPROVED: _____

TEST: NO. APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN COMPONENTS. CONNECTOR, SEAR ENGAGEMENT = .008 MIN. IS .020 ALSO FOUND METAL CHIP BETWEEN TRIGGER & CONNECTOR.

COMPLAINT: WILL NOT FIRE.

INCIDENT: FOLLOWS DOWN.

COMMENTS: THE METAL CHIP BETWEEN THE TRIGGER AND CONNECTOR REDUCED THE CONNECTOR-SEAR ENGAGEMENT TO ZERO CAUSING THE FOLLOWS DOWN.

PLAINTIFF'S
EXHIBIT

3230

AL 0029762