

Customer - 03/07/2002 04:01 PM
Remington recently repaired (repaired #RE00036567) rifle serial number
A6806957 REPLACEMENT E6625977.

News reports have raised concern about the bolt lock of some rifles which
could cause discharge while safety is still ON.

Please advise if the above rifle is free of any defects which could cause
accidental discharge of the rifle as it is today; after the above repairs
have been made.

Remington has always shown to me the greatest concern for customer service
and safety. I am appreciative of my contacts with Remington.

Question Reference #020307-000106

Contact Information: cunninghamwanda@cs.com
Date Created: 03/07/2002 04:01 PM
Last Updated: 03/13/2002 02:05 PM
Status: waiting