```
never
> repaired as part of that recall, then a new trigger assembly without a > bolt-lock feature will be installed. This change will be made at no cost
to
> you.
> You will need to send your firearm to our factory at the address below:
> Remington Arms Company, Inc.
> Ilion Firearms Plant
> Attention: BL Safety Program
> 14 Hoefler Avenue
> Ilion, NY 13357
> Customer (Leon Garfield) - 03/10/2002 05@28_PM
> My Model 600 does not have the V stamped in the trigger as indicated by
the
> recall in 1979. Can you tell me if my gun should have this done??
> As I understand it the new bolt fix on the safety would be free if I have
to
> have the recall done on my rifle. Is this correct??
> Please let me know as soon as possible thank you Leon Garfield
> Question Reference #020310-000089
> Topic: Firearms
> Sub-Topic: Centerfire Rifles
> Contact Information: garf@kingcon.com
> Date Created: 03/10/2002 05:28 PM
             Last Updated: 03/11/2002 02:07 RM
                      Status: Waiting
> If your issue remains unresolved, please update this question at
http://remington.custhelp.com/cgi-bin/remington.cfg/php/enduser/acct_login_s
You may also update this question by replying to this message. Because > your reply will be automatically processed, you MUST enter your reply > in the space below. Text entered into any other part of this message
> will be discarded,
> [===> This is a reply to an older email that I had sent. I sent my gun
out
to you
via ups on 9/25/02 and was just wondering if you received it alright. I
have
not heard anything letting me know .. Thanks Leon <===]
> [===> Please enter your reply above this line <===]</p>
> We hope that this information will be helpful to you. If we > can be of further assistance, please contact us at > 1-800-243-9700, M=F, 9am-5pm EST.
> Remington Arms Co. -- America's Oldest Gunmaker
> 870 Remington Brive, Madison, NC 27025
> 1-800*243-9700 or 1*336-548-8700--FAX: 1-336-548-7801
> Visit us in Remington Country at http://www.remington.com/
```