

Customer Complaint

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: GOOD R #: 19457
 OUTSIDE WORK: SCOPE MOUNTED. DATE: 10-4-71

FROM: GEN. SPT. SUPPLY CO.FIRED AMMO TYPE: _____ SYRACUSE, N.Y.& CONDITION: _____ GUN #: 6279663PROOF: R.E.R.-E INSP.: 74 TEST: 87 CODE: E5 = 10/69HEADING: O.K. GR./CAL.: 3006BREECH OPENING: - CHECKED BY: G. PROSSERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGED OR BROKEN COMPONENTS.COMPLAINT: FIRES WHEN SAFE IS PUSHED OFF.

INCIDENT: _____

PLAINTIFF'S
EXHIBIT

3234

COMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BE
DUPLICATED ANY WAY. IT WAS NOTED AND VERIFIED
BY K. CHADWICK THAT THE CUSTOMER HAD ADDED
A LUBRICANT WHICH IS TOO HEAVY (THICK) TO THE
TRIGGER ASSEMBLY. THIS, IN COLD CLIMATES WOULD
CAUSE A MALFUNCTION SUCH AS THAT CLAIMED BY
THE CUSTOMER.

AL 0029766